

Packing Instructions - Sea



As a guide, Steatite has prepared the below packing instructions to aid with the packing of returned products to our facility. Ultimately, the responsibility for shipping these items is on the consigner and, as such, we would recommend consulting the current regulations prior to any shipment so that compliance can be assured.

Steatite Requirements

Photos showing the internal and external of the return(s) **must** be sent to BATS-Recycling@steatite.co.uk for reviewing prior to any despatching.

Steatite Requirements

- All exposed surfaces of the battery(s) are safely and correctly covered, and there is no exposed metal.
- All sharp protruding parts of the battery(s) have been removed or covered.
- All lead assemblies are covered and must be taped to the pack. **Trailing leads are NOT acceptable.**
- The chemistry is clearly shown on the box (**Do not mix batteries with different chemistry in one box**).
- The boxes must be UN standard. (**Box must withstand a drop from 1.2m from any direction**).
- Sufficient Vermiculite (**loose or bags**) must be used in the disposal containers containing lithium waste cells. Boxes must be tightly filled with any other packing material (**shredded cardboard, bubble wrap or other**), so that the contents of the box **DO NOT** shift during any activity during the transport.
- Use as few boxes as possible. Maximum box weight 25kg, unless agreed in writing prior to collection.

Chemistry Specific Guidelines:											
Alkaline	Lithium Metal	Lithium Ion	Nickel Metal Hydride								
Not classified as Dangerous Goods.	<p>Packing Instruction P903 FOR ANY FERRY OR SEAFREIGHT ALWAYS USE A DANGEROUS GOODS NOTE, AS A SIGNED CERTIFICATION OF COMPLIANCE MUST BE PROVIDED.</p> <div style="text-align: center;">  <p>UN3090 LITHIUM METAL BATTERIES HANDLE WITH CARE</p> <p>REPORT ANY DAMAGE TO PACKAGE DO NOT USE WATER TO EXTINGUISH A FIRE</p> <table style="width: 100%; border: none;"> <tr> <td style="width: 50%;">SHIPPER</td> <td style="width: 50%;">CONSIGNEE</td> </tr> <tr> <td colspan="2" style="font-size: small;"> STEATITE LTD Unit 17 Northern Way Cropmead Industrial Estate Crewkerne, Somerset TA18 7HU UNITED KINGDOM </td> </tr> </table> <p>GROSS WT _____ KGS NET WT _____ KGS</p> </div>	SHIPPER	CONSIGNEE	STEATITE LTD Unit 17 Northern Way Cropmead Industrial Estate Crewkerne, Somerset TA18 7HU UNITED KINGDOM		<p>Packing Instruction P903 FOR ANY FERRY OR SEAFREIGHT ALWAYS USE A DANGEROUS GOODS NOTE AS, A SIGNED CERTIFICATION OF COMPLIANCE MUST BE PROVIDED.</p> <div style="text-align: center;">  <p>UN3480 LITHIUM ION BATTERIES HANDLE WITH CARE</p> <p>REPORT ANY DAMAGE TO PACKAGE DO NOT USE WATER TO EXTINGUISH A FIRE</p> <table style="width: 100%; border: none;"> <tr> <td style="width: 50%;">SHIPPER</td> <td style="width: 50%;">CONSIGNEE</td> </tr> <tr> <td colspan="2" style="font-size: small;"> STEATITE LTD Unit 17 Northern Way Cropmead Industrial Estate Crewkerne, Somerset TA18 7HU UNITED KINGDOM </td> </tr> </table> <p>GROSS WT _____ KGS NET WT _____ KGS</p> </div>	SHIPPER	CONSIGNEE	STEATITE LTD Unit 17 Northern Way Cropmead Industrial Estate Crewkerne, Somerset TA18 7HU UNITED KINGDOM		<p>Less than 100Kg per container Special Provision 963 which allows non-regulated shipment.</p> <p>More than 100Kg per container Dangerous Goods Declaration (you need to book it with the carrier as UN 3496).</p> <p>Class 9 Label is not required on the Package.</p>
SHIPPER	CONSIGNEE										
STEATITE LTD Unit 17 Northern Way Cropmead Industrial Estate Crewkerne, Somerset TA18 7HU UNITED KINGDOM											
SHIPPER	CONSIGNEE										
STEATITE LTD Unit 17 Northern Way Cropmead Industrial Estate Crewkerne, Somerset TA18 7HU UNITED KINGDOM											

 [Packing_Instructions_Sea_05_2023.pdf](#)